

## 1WTH\_PRB - SENSOR PINOUT

- The two wires go to the 2 center pins of the RJ12 plug
- The 1-wire Data line is the RED wire, which goes to pin-3 of the RJ12 plug.
  - Pin3 is the left pin of the two middle pins when inserting the wires into the RJ12 plug with the tab down and the open end toward you.
- The ground/voltage line is the WHITE wire, which goes to pin-4 of the RJ12 plug.
  - Pin4 is the right pin of the two middle pins when inserting the wires into the RJ12 plug with the tab down and the open end toward you.